



PRODUCT DATASHEET

Floor cleaning - Wipe and care

Wetrok OWETOL

Soap-based non-slip (DIN 18032 certified) solvent-free wipe and care product





Wetrok OWETOL



pH value (Concentrate): 9–10

Important ingredients:

Surfactants, Soap, Fragrances, Colourants, Preservatives

Recommended dosage:



Maintenance cleaning

0.05 – 0.1 l/10 l

METHODS
finder



APPLICATION

- Soap-based mopping care
- For maintenance cleaning of all water-resistant floor coverings and surfaces (PVC, natural and artificial stone, clinker, linoleum, oiled wood floors, natural rubber, etc.)

PROPERTIES

- Low lather
- Conforms to DIN 18032
- Slightly alkaline
- Solvent-free
- Lightly scented

RECOMMENDED APPLICATION METHOD

Damp wiping (by hand, using a bucket)

Soak the cloth with cleaning solution and then wring it out well. Wipe the surface with a damp cloth.

Scrub drying in a single work step

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub-dry the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush.

Wet mopping, single work step

Remove any loose dirt (e.g. dust-binding mopping/dry vacuuming). Soak the mop with cleaning solution, wring it out well, or use a pre-wetted mop. Wet mop the floor covering.

STORAGE

Store in original container at 15 to 25°C and protected from sunlight. Keep container closed when not in use. Store in original container at 15 to 25°C with good ventilation and protected from sunlight. Keep container closed when not in use.

Durability (unopened): 24 Month

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.