


Filling pores Protective treatment



	Description		
Definition / objective	Applying the pore filler to the floor coverings using the application tool with a cover. Suitable for porous, absorbent, water-resistant, non-textile floor coverings.		
Preparatory work	Se	lect suitable products to match the surface to be protected (type / square metres).	
	Pu	t up the warning sign.	
		mpletely remove stubborn dirt, care products and protective treatments with the suitable aning method as needed (e.g. wet scrubbing and wet vacuuming).	
		ow the floor covering to dry completely as needed.	
	Ch	eck the absorbency of the floor covering: Perform a water test.	
	Re	move any loose dirt (dust-binding mopping or dry vacuum cleaning).	
Main task	ap	ur a little bit of undiluted pore filler onto the floor and use the application tool with the cover to ply it evenly, moving in slightly overlapping passes (circular motion). Leave to soak, distribute y excess pore filler. Work backwards towards the exit.	
		apply additional passes, pour a little pore filler onto the wet area and spread it as described ove. Repeat this step until the entire area has been treated.	
	Alv	vays lift up the application tool from the floor like "an airplane taking off" at the end.	
		ow the floor covering to dry completely .	
		eck whether the protective treatment is sufficient: Perform a water test . peat the protective treatment as needed.	
	Pe	rform a visual check.	
Final steps	Remove the warning sign once the floor covering is dry.		
	Rinse the cover and wash it in the washing machine.		
	Dispose of any waste.		
	Clean the cleaning equipment and replace as needed.		
Comments	 Wear the personal protective equipment (PPE) required by company regulations, safety data sheets and / or instructions for use. Always check in advance which product meets your requirements (see Wetrok Cleaning & Care Instructions). Wetrok AG accepts no liability for damage caused by improper use or incorrect product selection. 		