

Floor cleaning - Maintenance cleaners

# **Wetrok Ceratop**

High-performance maintenance cleaner - the specialist for porcelain stoneware and microporous floor coverings





## **Wetrok Ceratop**









pH value (Concentrate): 12.5-13.5

## Important ingredients:

Surfactants, Soap, Base, Fragrances, Preservatives

## Recommended dosage:

3

Maintenance cleaning 0.05 -0.1 |/10 |



Intermediate cleaning

0.2–0.5 1/10 1

METHODS finder



## **APPLICATION**

- · High-performance maintenance cleaner
- For maintenance cleaning of hard and alkali-resistant floor coverings (ceramic tiles, natural and artificial stone, clinker, etc.)
- Especially suitable for porcelain stoneware and microporous floor coverings

#### **PROPERTIES**

- Low lather
- Highly alkaline
- Solvent-free
- Lightly scented

## **RECOMMENDED APPLICATION METHOD**

## Scrub drying in a single work step

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub-dry the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush.

## Wet mopping, single work step

Remove any loose dirt (e.g. dust-binding mopping/dry vacuuming). Soak the mop with cleaning solution, wring it out well, or use a pre-wetted mop. Wet mop the floor covering.

## **STORAGE**

Store in original container at 15 to 25°C and protected from sunlight. Keep container closed when not in use.

Durability (unopened): 24 Month

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.

