

Food/drink industry and industrial cleaning - Acidic foam cleaners

Wetrok Ketacid Brillant

The gentle acidic foam cleaner for removing limescale





Wetrok Ketacid Brillant









pH value (Concentrate): 1-2

Important ingredients: Surfactants, Acid, Solvents

Recommended dosage:



Foam cleaning 0.3–0.5 I/10 I

METHODS finder



APPLICATION

- · The gentle acidic foam cleaner
- For removing limescale
- For maintenance cleaning of washable and acid-resistant surfaces and equipment (filling and packing plants, tanks, pipework, walls, floors, etc.)
- · Application: foodstuffs industry

PROPERTIES

- High-lather
- Highly acidic
- Unscented

GOOD TO KNOW

 Foaming devices are not suitable for storing liquids, empty and rinse out daily whenever in use

PLEASE NOTE

- Not suitable for acid-sensitive surfaces (aluminium, clinker, etc.)
- Moisten non acid-resistant grout material with water before use

RECOMMENDED APPLICATION METHOD

Foam cleaning

Moisten surface to be cleaned with water thoroughly before use. Then apply the cleaning solution as a foam using a foaming device (using either a high or low-pressure device) starting at the bottom and working to the top. Allow the product to take effect as needed, without letting it dry. Work the cleaning solution in using an edge cleaning tool and white pad or Microsol fibre pad. Then rinse with water.

STORAGE

Store in original container at 15 to 25° C and protected from sunlight. Keep container closed when not in use.

Durability (unopened): 24 Month

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.

