



# PRODUCT DATASHEET

Kitchen cleaning - Maintenance cleaners

## Wetrok Poxex

High-performance kitchen maintenance cleaner for removing animal and vegetable grease and oils - suitable for machine use





# Wetrok Poxlex



**pH value (Concentrate):** 10–11

**Important ingredients:**

Surfactants, Soap, Chelating agents, Preservatives

**Recommended dosage:**



**Maintenance cleaning**

0.05 – 0.1 l/10 l



**Intermediate cleaning**

0.2–0.4 l/10 l

**METHODS  
finder**



**APPLICATION**

- High-performance universal cleaner
- Cleaner for removing animal and vegetable grease and oils.
- For cleaning alkali-resistant surfaces and floor coverings (PVC, natural and artificial stone, clinker, asphalt, etc.)
- For cleaning in food processing areas (canteens, restaurants, industrial and manufacturing plants)

**PROPERTIES**

- Non-foaming
- Slightly alkaline
- Unscented
- Solvent-free

**PLEASE NOTE**

- Rinse all work implements as well as the tank and conduit systems of automatic scrubbers with clear water after use

**RECOMMENDED APPLICATION METHOD**

**Scrub drying in a single work step**

Pour the cleaning solution into the fresh water tank. Remove any loose dirt by means of dust-binding mopping/dry vacuuming. Scrub-dry the floor covering thoroughly with a scrubber-dryer and a suitable pad or brush.

**Wet mopping, single work step**

Remove any loose dirt (e.g. dust-binding mopping/dry vacuuming). Soak the mop with cleaning solution, wring it out well, or use a pre-wetted mop. Wet mop the floor covering.

**Wet wiping (by hand)**

Wash the dirty surface with cleaning solution. Wet scrub using a suitable hand pad or brush. Use a cloth to remove the dissolved dirt and the remaining cleaning solution. Rinse the cleaned surface with clean, cold water and wipe it dry as needed.

**STORAGE**

Store in original container at 15 to 25°C and protected from sunlight. Keep container closed when not in use. Protect against frost.

*Durability (unopened): 24 Month*

Wetrok AG shall have no liability whatsoever for damage caused by incorrect use. Observe special cleaning and care instructions from the floor covering manufacturer.